

INFORMATION AND CARE FOR YOUR SINGLE SIDED LACQUER MASTERS (SSM)

Recommended Conditions for Shipping, Storage, Plating, etc.

Master Storage

Temperature..... 70+10 deg. F (21+5.5 deg. C)
Humidity..... 50+20%

Shipping

Uncut masters: Not to exceed 110 deg. F (43 deg. C)
Cut masters.....70+10 deg. F (21+5.5 deg. C)

Maximum time between cutting and plating:

As short as possible. *Optimum results if under 72 hours

Preferred Cutting Side: The side without the stamped quality code. The other side, although frequently cuttable, may have physical defects in cutting area.

Cutting Area: Defined as the area one (1") inch from the outside edge and two (2") inches from the center. (see diagram)

